



2400 Central Parkway, Suite R
Houston, TX 77092-7712
Phone: (713) 688-2777
Fax: (713) 688-2818
Email: houlmet@swbcfl.net

TO: International Metalizing & Coatings
7414 Bayway
Baytown, Texas 77520
ATTN: Marvin Wright

TEST NO: 769-03
P.O. NO
DATE 10-3-03


DATE OF TEST: 10-3-03
REPORT OF BOND SHEAR TEST

MATERIAL / DESCRIPTION: One (1) set of bond caps
IDENTIFICATION: 10/2
DATE RECEIVED: 10/2/03
SPECIFICATIONS: Client Instructions
TEST EQUIPMENT: T.O. S/N 120990-1

TECHNICIAN: Ronald R. Richter
PROCEDURE: HML-TTM-1-94 Rev. 1
COMPLIANCE:

BOND SHEAR TEST RESULTS

SPECIMEN NO.	DIAMETER INCHES	SQ. AREA INCHES	TOTAL LOAD LBS.	TENSILE PSI	FAILURE MODE
769-03					
#2 (10/2)	1.000"	.7854	5,190	6,608	Split coating



WITNESSED BY:
Tommie Gullett *Tommie Gullett zcc*

REVIEWED BY:
Brenda K. Any

R. Richter
RONALD R. RICHTER
PRINCIPAL/QA MANAGER